

# FITNESS CERTIFICATE

To be filled by the Inspecting Officer (Asst. Engineer)

(Re: G.O. Ms. 29770/PWD Dt. 23-01-1970)

- 1 Name of the Officer
- 2 Name of the School
- 3 Location with name of Education District/ Sub District
- 4 Classification of Building as specified in column 4 of the application for fitness certificate and size

ARUN TITTY H.O

Mahatma Gandhi Memorial Model School  
Ayyasoo P.O, Varkala, Alappuzha

- 1) Main bldg (3 storied) - 262' x 22' x 11'
- 2) Auditorium (3 storied) - 100' x 62' x 16'
- 3) Primary 1 bldg (3 storied) - 180' x 42' x 11'
- 4) Primary 2 bldg (3 storied) - 75' x 61' x 11'
- 5) Primary 3 bldg (3 storied) - 75' x 66' x 11'

5. Period for which the certificate is issued

2020-21

6. Nature of defects, if any

- a) Foundation and basement
- b) Superstructure
- c) Doors and Windows
- d) Wood work wrought and put up
- e) Roof
- f) Flooring
- g) Miscellaneous (Cracks, etc.)

} Nil

7. Any major defects noticed which will render the building unsafe in any manner

Nil

8. Whether maintenance works have been done properly

Yes

9. Whether the structure is sound or not for conducting classes

Structures are sound - as completing classes under normal weather conditions


Note: 1. The stability of the structure should be examined also with reference to location, altitude, intensity of wind, exposure of flood etc. 2. Any additional observations if deemed necessary for the certificate may be furnished separately with this certificate.

## CERTIFICATE

certified that the school building was inspected by me on 11/09/2020 and found to be fit / ~~unfit~~ to conduct classes, for the period 2020-21 for the reasons stated above.

Place Elakamon

Date 11/09/2020



Assistant Engineer  
**ARUN TITTY H.O.**  
Assistant Engineer  
L.S.G.D. Section  
Elakamon G. P.